

(2)

#15 Page 3 Power


Lot Layout and 1st floor



note looks in patches suggest infestation with rats

The linen closet on first floor about 8' x 10' x 2 1/2' ft. Has considerable storage space.

Kitchen has electric stove which works good. Storage cabinet



Note

one can walk below either side of 1st floor to rear

Door small
There is a large airy wine cellar 27 x 15 suitable for storage of all types of Hosp. Supplies - Floor Dressing sitting, House in ex-ellent Repair all Plumbing works.

Phone

about 11 x 24' outside door

each room downstairs - 1 electric outlet. Large rear room has 3,


2 spigots in kitchen downstairs, 1 in hallway

#15 Plage Fleurie 2nd floor

Wiring exposed in upper stair landing - will require 5 yd insulated wire and wood moulding to cover (30')

Wiring exposed - possibly this is secret radio outfit. Moulding needed (20')

Wiring exposed in "duty" room



Walls of upper hall have deep cracks suggesting a sagging of floor.


2 sockets } missing
2 bulbs } on 2nd floor

(4)

3.

#15 Plage Fleuve Roof

Gravel Covered - No leaks
Good condition



No electricity -
There is some old
wiring